UNITED

LABORATORIES

Responsible InnovationTM - **SOLAR GOLD Slime** and **Grease Cutter** harnesses the power of nature's resources to provide a bio-based blend that is uniquely suited for degreasing applications in wastewater treatment facilities and is readily biodegradable.

- NPE-Free.
- Non-caustic.
- Non-corrosive.
- Contains no petroleum distillates.
- Contains no chlorinated hydrocarbons.
- Deodorizes with fresh citrus scent.

COLLECTION SYSTEM

LIFT STATIONS — Mix 1 part of **SOLAR GOLD Slime and Grease Cutter** with 30 parts of water and spray on sidewalls. **United 637** solubilizes and cuts oil, grease, scum and slime build-up off the walls, so it can be easily flushed away.

For a product which layers the top of the lift station and stays there working, there's United 493 Lift Station Maintainer

WASTEWATER TREATMENT PLANTS
"CHOCOLATE FOAM" Controllant: For hand sprayed application, mix 1 part of United 637 with 10 parts of water. The A176 Chapin sprayer equipped with a fan tip (A180) is recommended. Apply the diluted product directly to foam for immediate knockdown. For application by automatic jet-spray system, mix 1 part of United 637 with 30 parts of water. Apply the diluted product directly to the foam for immediate knock-down.

Use United 53 DEFOAMER to knock down detergent foam.

SOLAR GOLD



Slime and Grease Cutter

WARNING
KEEP OUT OF REACH OF CHILDREN.
See other cautions on back/side panel.

PRECAUCION AL USARIO: Si usted no puede leer Ingles, pregunte a alguien que le traduzca esta etiqueta para usted antes de uso.

Manufactured and Sold Exclusively By:
UNITED LABORATORIES, INC.
320 37th Avenue • St. Charles, IL 60174
1-800-323-2594 • www.unitedlabsinc.com

WARNING: Causes skin irritation. May cause an allergic skin reaction. Flammable liquid and vapor. May be harmful if swallowed. May be harmful in contact with skin.



Wear protective gloves/protective clothing/ eye protection/face protection. Wash face, hands and any exposed skin thoroughly after handling. Avoid breathing fume/mist/vapors/spray. Contaminated work clothing must not be allowed out of the workplace. Keep away from heat/sparks/open flames/hot surfaces. — No smoking. Keep container tightly closed. Ground/bond container and receiving equipment. Use explosion-proof equipment. Use only non-sparking tools. Take precautionary measures against static discharge. IF ON SKIN (or hair): Remove/ Take off immediately all contaminated clothing. Rinse skin with water/shower. Wash contaminated clothing before reuse. If skin irritation or rash occurs: Get medical advice/attention. In case of fire: Use CO2, dry chemical, or foam for extinction. Store in a wellventilated place. Keep cool. Dispose of contents/ container in accordance with local/regional/national and international regulations.

ADDITIONAL FIRST AID MEASURES:

IF IN EYES: Immediately flush with plenty of water for at least 15 minutes while holding eyelids open. Get prompt medical attention.

IF INHALED: Remove to fresh air. If symptoms develop, seek medical attention. If not breathing, give artificial respiration.

IF SWALLOWED: Call a poison center or doctor/physician if you feel unwell. Rinse mouth.

CONTAINS (CAS#): d-Limonene (5989-27-5)

An SDS for this product is available through United's website, www.unitedlabsinc.com, providing 24 hour access. Please read the SDS carefully and follow all directions when using or handling this product. Never reuse empty containers. Incompatible materials may adversely react.